


$I \text{ charge[mA]} = 1000 / R102[\text{kOhm}]$
 STAT=L -> Charging
 STAT=H -> Charge Complete
 STAT=HiZ -> Shutdown

All resistors in footprint size 0603.
 Components marked "N.M." = not mounted.

Close JP104 only AFTER the MCU has been programmed - to secure UPDI against unwanted activation.

R117 and R118 should be adapted for actual LED brightness



VFDWATCH, hw V2.1

<http://www.jsykora.info/vfdwatch>
J. Sykora, 2019

Sheet: /
 File: vfdwatch2.sch

Title:

Size: A3	Date:	Rev:
KiCad E.D.A. kicad 5.0.2-5.fc29		Id: 1/1